



# Prestige and sports car specialists.

## Servicing Costs

## BMW – Latest Models

Here at GC Motors we pride ourselves in being able to offer main dealer facilities at specialist dealer prices, we are confident that as one of our valued customers you can enjoy up to 50% off main dealer servicing costs for your BMW without having to compromise on quality or level of service.

### 1 Series / 3 Series / Z4 / X3

	Petrol	Diesel
🔧 Inspection as per Manufacturer's Guidelines.	£80.00 Inc vat	£80.00 Inc vat
🔧 Oil Service as per Manufacturer's Guidelines.	£105.00 Inc vat	£115.00 Inc vat
🔧 Major Service as per Manufacturer's Guidelines.	£250.00 Inc vat	£275.00 Inc vat
🔧 Pollen Filter Change as per Manufacturer's Guidelines.	£55.00 Inc vat	£55.00 Inc vat
🔧 Brake Fluid Change as per Manufacturer's Guidelines.	£50.00 Inc vat	£50.00 Inc vat

### 5 Series / 6 Series / 7 Series / X5

	Petrol	Diesel
🔧 Inspection as per Manufacturer's Guidelines.	£80.00 Inc vat	£80.00 Inc vat
🔧 Oil Service as per Manufacturer's Guidelines.	£115.00 Inc vat	£130.00 Inc vat
🔧 Major Service as per Manufacturer's Guidelines.	£280.00 Inc vat	£295.00 Inc vat
🔧 Pollen Filter Change as per Manufacturer's Guidelines.	£60.00 Inc vat	£60.00 Inc vat
🔧 Brake Fluid Change as per Manufacturer's Guidelines.	£50.00 Inc vat	£50.00 Inc vat

### M Sport 3 Series / M Sport Z4

	Petrol
🔧 Inspection as per Manufacturer's Guidelines.	£80.00 Inc vat
🔧 Oil Service as per Manufacturer's Guidelines.	£200.00 Inc vat
🔧 Spark Plug Change as per Manufacturer's Guidelines.	£195.00 Inc vat
🔧 Pollen Filter Change as per Manufacturer's Guidelines.	£65.00 Inc vat
🔧 Brake Fluid Change as per Manufacturer's Guidelines.	£50.00 Inc vat

### M Sport 5 Series / M Sport 6 Series

	Petrol
🔧 Inspection as per Manufacturer's Guidelines.	£80.00 Inc vat
🔧 Oil Service as per Manufacturer's Guidelines.	£215.00 Inc vat
🔧 Spark Plug Change as per Manufacturer's Guidelines.	£250.00 Inc vat
🔧 Pollen Filter Change as per Manufacturer's Guidelines.	£70.00 Inc vat
🔧 Brake Fluid Change as per Manufacturer's Guidelines.	£50.00 Inc vat

The service pricing above is as accurate as possible however it is subject to change depending on the specific requirements of the vehicle as indicated by the vehicle's I-Drive system, if you are unsure then please do not hesitate to contact us.

Ripon Road, Harrogate, North Yorkshire, HG1 2BX

Tel: 01423 500017

Fax: 01423 530547

Email: [andre@gcmotors.co.uk](mailto:andre@gcmotors.co.uk)

Web: [www.gcmotors.co.uk](http://www.gcmotors.co.uk)



# Prestige and sports car specialists.

## Servicing Costs

## BMW – Earlier Models

Please be aware that we service and repair a wide variety of makes and models and so if your vehicle is not listed below please contact us for servicing costs or an individual quotation on 01423 500017 we are always happy to help.

### 3 Series / Z3 / X3

	Petrol	Diesel
Oil Service as per Manufacturer's Guidelines.	£100.00 Inc vat	£105.00 Inc vat
Inspection 1 Service as per Manufacturer's Guidelines.	£135.00 Inc vat	£145.00 Inc vat
Inspection 2 Service as per Manufacturer's Guidelines.	£240.00 Inc vat	£265.00 Inc vat

### 5 Series / 7 Series / X5

	Petrol	Diesel
Oil Service as per Manufacturer's Guidelines.	£100.00 Inc vat	£115.00 Inc vat
Inspection 1 Service as per Manufacturer's Guidelines.	£140.00 Inc vat	£150.00 Inc vat
Inspection 2 Service as per Manufacturer's Guidelines.	£250.00 Inc vat	£265.00 Inc vat

### M Sport 3 Series / M Sport Z3

	Petrol
Oil Service as per Manufacturer's Guidelines.	£150.00 Inc vat
Inspection 1 Service as per Manufacturer's Guidelines.	£185.00 Inc vat
Inspection 2 Service as per Manufacturer's Guidelines..	£600.00 Inc vat

### M Sport 5 Series

	Petrol
Oil Service as per Manufacturer's Guidelines.	£165.00 Inc vat
Inspection 1 Service as per Manufacturer's Guidelines.	£195.00 Inc vat
Inspection 2 Service as per Manufacturer's Guidelines..	£615.00 Inc vat

The service pricing above is as accurate as possible and for the earlier models includes brake fluid change and spark plug change where appropriate however some vehicles may be fitted with long life spark plugs which will incur an additional cost when due for change, if you are unsure then please do not hesitate to contact us.

Ripon Road, Harrogate, North Yorkshire, HG1 2BX

Tel: 01423 500017

Fax: 01423 530547

Email: [andre@gcmotors.co.uk](mailto:andre@gcmotors.co.uk)

Web: [www.gcmotors.co.uk](http://www.gcmotors.co.uk)